

HOW TO ORDER

PRIME D

X R D - A B C D E

-17.8

For blue display please contact Dixell

A	B	C	D	E
Power supply	Input	Buzzer	Measurement unit	Compressor output
2 = 24Vac 4 = 110Vac 5 = 230Vac	P = PTC N = NTC	0 = No 1 = Yes	C = °C F = °F H = °C heating only for XR10D L = °F heating only for XR10D	0 = 8A 1 = 20A