

HOW TO ORDER

XT11S

X T 1 1 S - A B C O N

-17.8

For blue display please contact Dixell

A	B	C
Power supply	Digits n°- measurement unit	Display update delay
0 = 12Vac/dc 1 = 24Vac/dc 4 = 110Vac 5 = 230Vac	0 = °C - integer 1 = °F - integer 2 = °C - decimal point	0 = no delay 1 = 1 min 2 = 3 min